

P.O. Box 1153
900 Overlander Road
Emporia, KS 66801 USA

GLENDO
CORPORATION

Phone: 620-343-1084 • Fax: 620-343-9640 • E-mail: glendo@glendo.com

www.glendo.com • www.grstools.com • www.accu-finish.com • www.handworker.com

ACCU-FINISH II CABINET MOUNTING PLATE ASSEMBLY


This mounting kit lets you mount the Accu-Finish Series II cabinet to a heavy steel plate instead of bolting it to the floor.

There are five each 3/8" - 16 UNC tapped holes in the mounting plate. Four of them are in an obvious rectangular pattern. Place the mounting plate on the floor so that the extra (fifth) 3/8" - 16 UNC hole is towards the back. Next, place the cabinet on the mounting plate, aligning the cabinet holes with the four rectangularly spaced 3/8" - 16 UNC holes on the mounting plate. Bolt the cabinet to the mounting plate using four 3/8" x 5/8" long hex bolts and the 3/8" flat washers.

The #10 - 32 x 1" long machine screws and #10 - 32 nuts are for leveling your cabinet on the floor using the four tapped #10 - 32 holes in each corner of the mounting plate. First, fully install a #10 - 32 nut on each #10 - 32 screw. Then, insert the screws with nuts through the top of the mounting plate using the four tapped holes in each corner. Now, adjust the depth of each screw to level your cabinet. Finally, lock the #10-32 screws in plate using the nuts.

For any questions or comments concerning this product, please call or fax.
Thank you for your business!

Glendo Corporation



CABINET MOUNTING BOLTS
3/8-16 X 5/8" HHB (4)
W/ WASHERS

MOUNTING PLATE LEVELERS
10-32 MACHINE SCREWS (4)
W/JAM NUTS

FRONT OF CABINET (DOOR SIDE)